zoopa | Q55 zepto Service information - Rotor replacement

Please note:

To ensure optimal flight characteristics, please regard the proper assembly and rotational direction of the propellers. The position of the marking (imprint/ stamp with letter A or B) can vary. It is placed on the up- or downside.

Flight direction from pilots view: **Forwards**



